

# Ceros<sup>®</sup> safety helmets

## Replacement accessories

### XP AirBridge<sup>®</sup> suspension system

17-19001



### IES AirBridge<sup>®</sup> suspension system

17-19002



### XP sweatband

17-20001



### IES sweatband

17-20002



### XP SwiftLock<sup>™</sup> wheel ratchet padding

17-25001



### K1C hygiene kit K2C, K1M, K1M magnet hygiene kit

17-28001

17-29001



# Ceros® safety helmets

## Replacement accessories

### Accessory compatibility

#### Replacement accessories

Product Name	Part #	XP200	XP250	XP200E	XP250E	XP450A	XP450AE	XP500IES	XP250IES
XP AirBridge® Suspension System	17-19001	◊	◊	◊	◊	◊	◊		
IES AirBridge® Suspension System	17-19002	◊	◊	◊	◊	◊	◊	◊	◊
Sweatband	17-20001	◊	◊	◊	◊	◊	◊		
IES Sweatband	17-20002							◊	◊
Wheel Ratchet Padding	17-25001	◊	◊	◊	◊	◊	◊	◊	◊

#### Earmuff accessories

Product Name	Part #	K1C	K2C	K1M	K1M Magnetic	K2M	K2M Magnetic
K1C hygiene kit	17-28001	◊					
K2C, K1M, K1M Magnet hygiene kit	17-29001		◊	◊	◊	◊	◊

◊ = Compatible  
◊ = Supplied as standard

*Distributed by:*



Protective devices do not provide unlimited protection. Some operations may require machine guards, face shields, special filter lenses, or other safety equipment. Safety helmets do not provide complete protection against hazards, and should only be used in conjunction with the prescribed safety equipment for the application as well as defined safety practices.